

# FIRMWARE HISTORY

## INTRODUCTION

Evolis is conducting for many years a general policy to improve the quality and features of his printer range. This document describes modifications and improvements from original firmware release 1426 to the latest available from Badgy website version 1757 released on December 2020.

## SUMMARY

### Related printers' models:

- **Badgy 100**
- **Badgy 200**

| VERSION HISTORY                | 2 |
|--------------------------------|---|
| Firmware version – 1757 (534F) | 2 |
| Firmware version – 1754 (CB62) | 2 |
| Firmware version – 1634 (9C62) | 2 |
| Firmware version – 1631        | 2 |
| Firmware version – 1626        | 2 |
| Firmware version – 1624        | 2 |
| Firmware version – 1605        | 2 |
| Firmware version – 1504        | 2 |
| Firmware version – 1443        | 3 |
| Firmware version – 1426        | 3 |

## VERSION HISTORY

04/12/2020

### **Firmware version – 1757 (534F)**

- Firmware version alignment

13/05/2020

### **Firmware version – 1754 (CB62)**

- Cleaning warning management (Pcsc / Rcsc added commands)
- Power supply voltage control (when power on printer)
- Ribbon management improvement (enable/disable ribbon synchronization when power on or exit from standby mode)
- Color (YMC) panel's contrasts improvement.

04/07/2017

### **Firmware version – 1634 (9C62)**

- Ribbon management improvement.

16/12/2016

### **Firmware version – 1631**

- Pre-heating mode improvement
- Internal memory data backup improvement

06/09/2016

### **Firmware version – 1626**

- Varnish quality improvement.

06/07/2016

### **Firmware version – 1624**

- Print head temperature regulation improvement.
- Print head signal management improvement.

18/02/2016

### **Firmware version – 1605**

- Color sensor adjustment process improvement.
- USB communication improvement.
- Technical test card printing process improvement.
- Add monochrome speed management.

02/02/2015

### **Firmware version – 1504**

- Sleep mode disable by default.
- USB device communication improvement (USB Certification OK).
- Color sensor adjustment improvement.
- Add automatic color readjustment if the ribbon synchronisation failed.

30/10/2014

**Firmware version – 1443**

- Black printing quality improvement (for color ribbon).
- Set USB to USB 2.0 full speed (USB Certification agreement).
- Design modification of the Technical Card (Internal font change).

26/05/2014

**Firmware version – 1426**

- Original firmware version.

**EUROPE - MIDDLE-EAST - AFRICA**

Evolis - 14 avenue de la Fontaine - ZI Angers-Beaucouzé  
49070 Beaucouzé - France  
T +33 (0) 241 367 606 - F +33 (0) 241 367 612  
[info@evolis.com](mailto:info@evolis.com)

**AMERICAS** - Evolis Inc. - Fort Lauderdale - [evolisinc@evolis.com](mailto:evolisinc@evolis.com)

**ASIA-PACIFIC** - Evolis Asia Pte Ltd - Singapore - [evolisasia@evolis.com](mailto:evolisasia@evolis.com)

**CHINA** - Evolis China - Shanghai - [evolischina@evolis.com](mailto:evolischina@evolis.com)

**INDIA** - Evolis India - Mumbai - [evolisindia@evolis.com](mailto:evolisindia@evolis.com)